

## ASBESTOS UPDATE

The district's ongoing asbestos program complies with the Federal Asbestos Hazard Emergency Response Act (AHERA) and has resulted in the following asbestos abatement projects since our last report.

- District-wide operation and maintenance floor tile replacement.
- See attachment for Accomsett MS, Barton Administration, HS East, Great Hollow MS, Smithtown Elementary.

The district has completed its tri-annual survey of all the buildings and continues its semi-annual surveillance requirements under the regulations of AHERA. This, combined with the district's ongoing maintenance program, has produced a list of operation and maintenance repairs on a district-wide basis. A summary of these repairs is included in each building's management plan.

Any individual may review a building's management plan by going to the school's main office and requesting it. Copies of all the schools' management plans are available for review at the district's central offices at 26 New York Avenue, Smithtown.

- **Accompsett Middle School: Joint Compound Abatement** - Room 101, Room 107, Room 109, Room 111, Room 113, Room 117, Room 119A Backroom, Room 119C, Room 121, Room 125, Room 127, Room 129, Room 131, Room 137, Room 237, Room 231, Room 229, Room 227, Room 225, Room 221, Room 219, Room 217, Room 213, Room 211, Room 209, Room 207, Room 201  
Floor Tile Abatement - Room 102, Room 104, Room 109, Room 106, Room 113, Room 132A, Room 132A Science Storage (118), Stairwell near Room 127, Room 112, Room 114, Room 137, Room 116, Room 237, Room 235, Room 233 Teacher Storage, Room 231, Room 229, Room 214 English Office, Room 227, Room 225, Room 221, Room 219, Room 217, Room 213, Room 211, Room 209, Room 207, Room 207 Teacher's Storeroom, Room 203, Room 201, Library Office AV Room, Library Room 206 Computer Lab Room 206 Staff Computer Lab, Library Room 212A
- **Barton Administrative Offices: Floor Tile Abatement Superintendent's Office**
- **Smithtown High School East: Ceiling Tile Mastic** - School Store, Room 111, Room 109, North Large Stairwell (1st Floor - Roof), Stairwell (Large South), Girls Bathroom, Boys Bathroom, Library Vestibule, Vestibule And Corridor Between Library And Little Theatre, Main Cafeteria, Corridor (Doors To Guidance Hallway - Ramp Outside Main, Corridor (Ramp Outside Main Office - Main Office), Back Stairwell To Main Cafe  
Floor Tile Abatement - Room 111, Room 109  
Door caulking Abatement - Auto Shop Hallway Exit
- **Great Hollow Middle School: Floor Tile Abatement** - Assistant Principal 110, 109C, School Counselor 109A, School Counselor 109A Closet, Room 108, 107F, Closet 107C, Closet 106G, Boy's Locker Room Office, Room 140, Storage 138, Storage 137, Room 125, Room 125A, PTA 120, PTA 121, Copy Room 124, Room 129B, Media Center Server Room 248, Storage 246, Storage 245, Computer Lab 244, Room 241, Room 240, Room 238, Room 237, Room 236, Room 236A, Room 236 Closet, Room 235, Room 232, Room 229, Room 223, Room 222, Room 221, Room 220, Room 218, Room 217, Room 211A, Room 210, Room 208, Room 209A, Room 204  
Pipe & Pipe Fitting Abatement - Room 220, Boiler Room 134B, Fan Room 1, Fan Room 2  
Vibration Cloth Abatement - Fan Room 1, Fan Room 2  
Hot Water Tank Insulation Abatement -Boiler Room 134B
- **Smithtown Elementary School: Floor Tile Abatement** - Room 30, Room 29, Room 28, Room 27, Room 26, Room 25, Cafeteria Kitchen Storage, Gym Storage, Gym Office, Room 12, Room 14, Room 15, Room 23, Room 17, Room 22, Room 18, Room 19, Room 20  
Ceiling Tile Mastic Abatement - Room 24, Room 23, Room 22, Room 21, Room 19, Room 20, Corridor from Room 20 To Offices  
Roof Abatement - Silver Built-Up Roofing System and Modified Granular Roofing System